AISIDEE		AIAOIWI	IONS			
Inspector:		1	11 /	• • • • • • • • • • • • • • • • • • • •		
	-1	aime i	N (cc	10010		ì
		MILLE 1	Y CC	IKC/2	 	
Date of Ins	ection:	A lilia	and the same of th			
	7-0-41-0114	15 11 116				1

Shift: 1st shift or I shift Time: 5AM

		0/10				
	Visual Mispection NORMAL Of			Comments		
	ABNORMAL					
Visible Emission From Shaker	NOR					
Visible Emission From						
Visible Emission From Discharge Conveyor System	NOR					

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 2/10/09

VISIBLE EMISSION NOTATIONS			•		
Inspector:		· ·			
Alex Bau	tiste,				
Date of Inspection:					
Ce/1/15					
Shift: 1st Shift or 2nd Shift	t Time:				•
		4:30pm			
. Unit	Vistali Vista		Co	imments	
	Natio Cathaia				
	LAWIRGHI				
	101				
Control of the Contro	ARTING ELIMINAL				
Visible Emission From Shaker					
Visible Lillission From Shaker	NOR				
Visible Emission From Discharge			•	•	18.00
Conveyor System	Non				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector: Prisone A Sand	chec				
Date of Inspection: 6/2/15					
Shift: 1st Shift or 2nd Shif	Time:	5:00 pm			
e Walth	Vfis(62)		Section of the second contract of the second	ninients	
	Hugideaquau Notawali				
100 mg/mg/mg/mg/mg/mg/mg/mg/mg/mg/mg/mg/mg/m	Or ABNORVIAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge					

Non

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System

VISIBLE EMISSION NOTATIONS			- .		
Inspector: Paul Land			_		
Date of Inspection:	5				
Shift: 1st Shift or 2nd Shift	t Time:	5 p			
Ühalic	vistal Linspertions Linspertions			ojmini entis	
	idy Aleintoirumvalo				
Visible Emission From Shaker	por				
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS						
Inspector: George A Sum	chre					
Date of Inspection: $6/3/15$						
Shift: 1st Shift or 2nd Shift	₹ Time:	5:00 AM				
Unité	Victori Victori			(Commtents		
	IN JANUAL Voit Albinioriuval					
Visible Emission From Shaker	Nor		2 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	24331. 3234. 3344. 3444. 3444. 3444. 3444. 3444. 3444. 3444. 3444. 3444. 3444. 3444. 3444. 3444. 3444. 3444.	Entered Courses to Secretary Constitution of the Constitution of t	Production of the Control of the Control
Visible Emission From Discharge Conveyor System	Nov				•	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: Alex Ba	Just SR			
Date of Inspection: (c/3)	115			
Shift: 1st Shift or 2nd Shift	t Time:	4:30pm		
, Unite	Vistali		nanteniis	
	MORMAL			
	oj <u>Abnormal</u>			
Visible Emission From Shaker	Nor	, market and the second and the second		
Visible Emission From Discharge		The state of the s		
Canyovar System	Aband	The state of the s		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.


VISIBLE EMISSION NOTATIONS			_		
Inspector: Wiltow Mis	zenlov 7				
Date of Inspection:	(5)				
Shift: 1st Shift or 2nd Shift	Time: <	500 SAW		·	
Obate.	Virteri Nispeationi <u>Normal</u>			immedis	
	OV ABINORUWAL,				
Visible Emission From Shaker	wormal,				
Visible Emission From Discharge Conveyor System	Worms		•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			_		
Inspector: Alex R	sautist SR				
Date of Inspection:	115				
Shift: 1st Shift or 2nd Shift	Time:	5 pm			
Uniti	Viistoiei ไม่เรื่อย์อย่างกับ		(4-18-466) 110-110-110-110-110-110-110-110-110-110	nini Eniss	
	INDIMMAL.				
	ABNORMAL				
Visible Emission From Shaker	NoR	· ·			
Visible Emission From Discharge		"Manufacture and the second se			
Conveyor System	N-10				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS			-1		
Inspector: Mile w Miz	enbor				
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	500 Am			
. Onitic	Variotali Valencia di Torri			nanienie P	
	LAMMACINI				
	/AISIMOJEIM/AIL:				
Visible Emission From Shaker	Normal				
Visible Emission From Discharge	0				
Conveyor System	Normal	}			


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.


VISIBLE EMISSION NOTATIONS			- 1		
Inspector: Alex Bar	History.		_		
Date of Inspection: 6/5/15					
Shift: 1st Shift or 2nd Shift	t Time:	Choun			
Uniti	Victori Nation sutoni Notemal Pot Manifornismal			Commichis and	
Visible Emission From Shaker	Nor				PAGE MENTAL PROPERTY.
Visible Emission From Discharge Conveyor System	Nor		-		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector: Jame M	CORCIA				
Date of Inspection: $6/7/65$			_		
Shift: 1st Shift or 2nd Shift	t Time:	5Am			
Unite	Virgiei 41 Inspeculant BINORMAL 101 ABINORMAL			Comments	
Visible Emission From Shaker	NOR	y maga dagawa (Palaceter and Color granulates (Palaceter or consumption).			
Visible Emission From Discharge Conveyor System	NOR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector:	13 ad 700				
Date of Inspection:	7-20 15				
Shift: 1st Shift or 2nd Shift		6',00pm			
Unit	vija Vijatesi Naspestina <u>MaisiMv4L</u>		Committee .		
	ior <u>ABNORWAL</u> ,		The second second		
Visible Emission From Shaker	NOC				
Visible Emission From Discharge Conveyor System	Noc	alleller			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			-		
Inspector: Amian S	alinas Dr				
Date of Inspection: $6-8-15$					
Shift: 1st Shift or 2nd Shift	Time:	5:00 Am			
(d)nike	u Visual Inspession Pokimkal Or			omma enus s	
Visible Emission From Shaker	ABNORMAL ///				
Visible Emission From Discharge Conveyor System	Nov	Same of the same o			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			_		
Inspector: Whow Mize	abore				
Date of Inspection: $G-8-1$	5)				
Shift: 1st Shift or 2nd Shift	Time:	5°0m			
Omic	Visibi±li Ninspi≙sullami		Gon	ninit=nins	
	<u>indrmal</u>	e de la companya de			
	di ABNORWAL				
Visible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	XI. a.l				
Conveyor System	1401 W 461	<u> </u>			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS		A			
Inspector: Smell(0					
Date of Inspection: June 9.	15				
Shift: 1st Shift or 2nd Shift	Time:	5:30 AM	<u>}</u>		
(Onsic	Visidāl il Milijaedilaini			omments	
	<u>NOHMAL</u> 6)				
Visible Emission From Shaker	n or		The state of the s		
Visible Emission From Discharge Conveyor System	non				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSIO	N NOTATIONS	
Inspector:		21
 · .	Wollen &	antee
Date of Inspection:	6.9-2015	
Shift: 1st Shift	or 2nd Shift	Time:

O niic	Vistri Notacijani <u>Notakwel</u> Voje ABINORIMAL	and Commitments	
Visible Emission From Shaker	Nor		
Visible Emission From Discharge Conveyor System	Nor		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			_		
Inspector:	all				
Date of Inspection:	-15				
Shift: 1st Shift or 2nd Shift	t Time:	5:00 pm		·	
Untic	Vistel Inspection <u>Nokimat</u>		100 1100 1100 1100 1100 1100 1100 1100	mmenus .	
Visible Emission From Shaker	roi Alinormial				
Visible Emission From Discharge	Nov				
Conveyor System	ror				


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.


VISIBLE EMISSION NOTATIONS				
Inspector: Smello				
Date of inspection: 6 - 10 - 1	5			
Shift: 1st Shift or 2nd Shift	Time:	5: PM		
Constructive of Security and Construction of the Security of Security of Security Security (Security Security S	A NO CONTRACTOR MANAGEMENT (NEW YORK) CONTRACTOR CONTRACTOR (NEW YORK)		i (Colminitatis)	
	Hapedimi Timosmal			
	abnormal			
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor	· · · · · · · · · · · · · · · · · · ·		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector:	John D.	Sandjusting Co., power			
Date of Inspection: (2-	-15				
Shift: 1st Shift or 2nd Shift	t Time:	500p			
Unita	vic. Virtuali Allinopestioni			namidados :	
	<u> </u>				
	ABNORWAL .				
Visible Emission From Shaker	∞				
Visible Emission From Discharge					
Conveyor System	1 101 W)				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Visible Emission From Discharge

Conveyor System

MOR

VISIBLE EMISSION NOTATIONS	Λ		_		
Inspector:	on Moke	rolling.			
Date of Inspection: (0-13-	-15				
Shift: 1st Shift or 2nd Shif	t Time:				
Onité	i in Vistrali Alikipendinin		r de Co	narnicaphis)	
	<u>involvimyall</u> voje				
Section 1 to 1 march 1 to 1 march	ABRIGRAMAL				
Visible Emission From Shaker	Nom				
Visible Emission From Discharge Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








VISIBLE EMISSION NOTATIONS				
Inspector: Damian Sal	linas Dr			
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shif	t) Time:	STOCK	 	
Units	Visual Lingoestian Volamval		iniments	
	ion Abnormal			
Visible Emission From Shaker	Nov			
Visible Emission From Discharge Conveyor System	Nor	_		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			_		
Inspector:	· Ildan				
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	t Time:	5:000m			
Unit Constitution of the Constitution of the C	Visual Inspection <u>NORMAL</u> or ABNORMAL		Gon Participant of the second	aments	
Visible Emission From Shaker	N ham				
Visible Emission From Discharge	1 Non				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.




VISIBLE EMISSION NOTATIONS				
Inspector: Smelko				
Date of Inspection: June 15	,15			
Shift: 1st Shift or 2nd Shift	Time:	200 PM		
Unit:	Visual Lhspectiani <u>NORMAL</u> Or ABNORMAL		Comments	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor	Name of the State		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.









Inspector: Garge A Sar Date of Inspection:	nchree				
Date of Inspection: 6/15/15					
Shift: 1st Shift or Znd Shift	t Time:	5:00pm	,		
Unit.	Visual Inspection <u>NORMAL</u> or ABNORMAL			Comments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nar				


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS					
Inspector: Sme 1100					
Date of Inspection: June 16,	15	and the state of the	renalistador		
Shift: (1st Shift) or 2nd Shift	t Time:	JPM			
Ulhiāc	Viigliel Lijispeationi Lijispiyiyyle			COmments	
	reg. Albinoriyas				
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.









Inspector: Garage	Surcher				
Date of Inspection: (g/17/15)	**				
Shift: 1st Shift or 2nd Shif	Time:	5:00xn	,		
Units	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nex				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.


(Stack SDS 04)

Inspector: Smelko		
Date of Inspection: June 17,15		
Shift: 1st Shift or 2nd Shift	Time: 5:00PM	-
. Unit	Visual	Comments

Unit.	Visual Inspection <u>NORMAL</u> or	Comments
Visible Emission From Shaker	ABNORMAL NOR	
Visible Emission From Discharge Conveyor System	nor	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.






(Stack SDS 04)

Inspector: George A Sunth Date of Inspection: (1866)	/ vce				
Date of Inspection: 6/18/15					
Shift: 1st Shift or 2nd Shift	Time:	8:00 Am	1		
Unit:	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	Nor	·			
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EI	MISSION	NOTATIONS
------------	---------	-----------

Inspector: Smelko				
Date of Inspection: June 19	15			
Shift: 1st Shift or 2nd Shift	Time:	5.90		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comment	
Visible Emission From Shaker	noR	**************************************		
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EN	IISSIUN.	NOTA	HONS
------------	----------	------	------

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

Inspect	or:	corsel Su	nher	All	
Date of	Inspection:				
Shift:	1st Shift	or 2nd Shift	Time:	2:00 pm	
Eng. 1	Üni		Visual Inspection	THE STATE OF	Comments

ABNORMAL

Non

Nor

• Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector:	Neword)		
Date of Inspection:	7-15			
Shift: (1st Shift) or 2nd Shift	Time:	5:00pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Commer	
Visible Emission From Shaker	Norm			
Visible Emission From Discharge Conveyor System	Nom			


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

D.1.12 SDS | Daily Visible Emissions Notations Per Each Daylight Shift

(Stack SDS 04)

VISIBLE EIMISSIGN NO INTITIONS					
Inspector: Odime N G	ocallia				
Date of Inspection: 6/11]		
Shift: 1st Shift or 2nd Shi	t Time:	5	1		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	Non				
Visible Emission From Discharge Conveyor System	Nox				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.




Inspector:	Smello	Parish Andrew	, services and a service and a		
Date of Inspection:	June 18.	15			
Shift: 1st shift	or 2nd Shift	Time:	6.Bopm		
Uni		Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission Fr	rom Shaker	nor			
Visible Emission Fr Conveyor System	rom Discharge	nor		·	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector: Smello				
Date of Inspection: June 18	15			
Shift: 15FShift or 2nd Shift	Time:	6.Bopm		
Unit h	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments.	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



(Stack SDS 04)

Inspector: George A Sunc	cher			
Date of Inspection: 6/22/15				
Shift: Ast Shift or 2nd Shift	: Time:	5:00 pm		
Unit	Visual	A Principal Control	, Comments	
	Inspection			
	<u>NORMAL</u>	100 miles		32 Maria (1924) (1924) Andrew Bernstein (1924) (1924) Inn 1924 (1924)
	or			
	<u>ABNORMAL</u>	and the second s		
Visible Emission From Shaker	Nar	·		
Visible Emission From Discharge				
Conveyor System	Nar			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS


Inspector: Smellc)			
Date of Inspection: Jun 23,1	-3-			
Shift: 1st Shift or 2nd Sh	Time:	SAM		
Unit	Visual Inspection Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	nop			
Visible Emission From Discharge Conveyor System	nor	Charles Transaction		

(Stack SDS 04)

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015







VISIBLE EMISSION NOTATIONS

VISIBLE EIVIISSION NOTATIONS				
Inspector: George A Souche	: :			
Date of Inspection: 6/23/15			·	
Shift: 1st Shift or 2nd Shift	t Time:	5.00 pm		
Unit a	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nar			
Visible Emission From Discharge	10			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System



(Stack SDS 04)

VISIBLE EMISSION NOTATIONS

Visible Emission From Discharge

Conveyor System

DOD Nos

Inspector: Greater HS.	mohor			
Date of Inspection: 6/24/15				
Shift: 1st Shift or 2nd Shif	t Time:	5:00pm		
Unit Control of the C	Visual Inspection NORMAL or ABNORMAL		omments	
Visible Emission From Shaker	Des Max			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Smelko					
Date of Inspection: June 25	, 15]		
Shift: 1st Shift or 2nd Shift	Time:	500AM	-		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comi	ments	
Visible Emission From Shaker	Nor	,			
Visible Emission From Discharge Conveyor System	nor	agent			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

	VISIBLE	EMISSION	NOTA	TIO	NS	
٠						

Visible Emission From Shaker


Conveyor System

Visible Emission From Discharge

Inspector: George	A Sanchez					
Date of Inspection:	25/15					
Shift: 1st Shift or	2nd Shift	Time: 5:00/	zm			
Unit	Vist Inspec NORN	tion and a supplied the		Co	pmments	
	or ABNOR					

Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



light Shift		

VISIBLE EMISSION NOTATIONS				
Inspector: Smelle				
Date of Inspection: June 98	015			
Shift: 1st Shift or 2nd Shift	Time:	5.00		
Unit services Unit services and services are services and services and services and services and services are	Visual 17 Inspection NORMAL or ABNORMAL		Comments:	
Visible Emission From Shaker	noc	STARROWN .		
Visible Emission From Discharge Conveyor System	nor	•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EMISSION NOTATIONS

Visible Emission From Discharge

Conveyor System

Wor

Nor

Inspector: Garge A. S Date of Inspection: 6/26/15	anchee			
Date of Inspection: 6/26/15				
Shift: 1st Shift or 2nd Shif	t Time:	5:00 pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments A second seco	
Visible Emission From Shaker	2			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EM	IISSION	NOTA	ATIONS
------------	---------	------	--------

Inspector: Sme	- الره				
Date of Inspection:	e 27,15				
Shift: 1st Shift or 2nd S	Shift Time:	500Am			
Unit L	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Personal Control of the Control of t	omments	
Visible Emission From Shaker	nor	entitations.			
Visible Emission From Discharg Conveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





Inspector: Greene A Some	hez				
Date of Inspection: 06/27/15	_]		
Shift: 1st Shift or 2nd Shift	t Time:	5200 pm]		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	Non				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





Inspector:	Smell	(0		1		
Date of Inspection:	nc 28,	け]		
Shift: 1st Shift or	2nd Shift	Time:	5'.00Am			
d Unit		Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Sh	aker	NOB				
Visible Emission From Dis Conveyor System	scharge	nop				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

٠	/ICIDI	_	- B 4	100		NIO	- 4 -	101	_
١	∕ISIBL	Ŀ.	FIVI	155	IUN	NO	IAI	I(I)II	5

Visible Emission From Discharge

Conveyor System

Nor

Inspector: George A Sanche				
Date of Inspection:				
Shift: 2st Shift or 2nd Shif	t Time:	5:00 pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Smello					
Date of Inspection:	19,17		1		
Shift: 1st Shift or 2nd Shift	Time: A	SAM]		
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		n Co	mments	
Visible Emission From Shaker	nor	Salatera Caraca.			
Visible Emission From Discharge Conveyor System	noR	**************************************			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Grose A Sanch Date of Inspection: GAY/15	et				
Date of Inspection: 6/24/15	_				
Shift: 1st Shift or 2nd Shif	t Time:	S. Oopn			
J. Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comr	ments in the second of the sec	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Smelko					
Date of Inspection: June 30	5				
Shift: 1st Shift or 2nd Shift	Time:	5AM			
Unit and the second sec	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Con	nments	
Visible Emission From Shaker	nor	,100 killings			
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Garge A S	nchez			
Date of Inspection: . G/30				
Shift: (1st Shift) or 2nd Shift	t Time:	5:00 pm		
Processing Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments.	
Visible Emission From Shaker	Nor	,		
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.